Maryland Historical Trust

Maryland Inventory of Historic Properties number: PG: 70-56 Name: MD 450 or Wall Decoupled Round Roun	-
MARYLAND HISTORICAL TRUST	_
Eligibility Recommended Eligibility Not RecommendedX	
Criteria: A B C D Considerations: A B C D E F G None	

Comments:

Reviewer, OPS:_Anne E. Bruder___

Reviewer, NR Program: Peter E. Kurtze

TRING TO

Date:__3 April 2001___

Date:__3 April 2001_

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

SHA Bridge No. 1601	Bridge name MD 450 over Abandoned Railroad	
LOCATION: Street/Road name and	number [facility carried] MD 450 (Annapolis Road)	
City/town Buena Vis	sta	Vicinity X
County Prince Georg	ge's	
This bridge projects ov	ver: Road Railway_X Water	Land
Ownership: State	X County Municipal Oth	er
National Regist	vithin a designated historic district? Yes ster-listed district National Register-determined-elignated district Other	gible district
Name of district		
BRIDGE TYPE: Timber Bridge: Beam Bridge: Stone Arch Bridge	Truss -Covered Trestle Timber-And	d-Concrete
Metal Truss Bridge _		
Movable Bridge: Swing: Vertical Lift	Bascule Single Leaf Bascule Multip	
Metal Girder_X Rolled Girder_ Plate Girder	Rolled Girder Concrete Encased X	=
Metal Suspension		
Metal Arch	-	
Metal Cantilever		·
Concrete: Concrete Arch_ Other	Concrete Slab Concrete Beam Rigid	I Frame

DESCRIPTION:			
Setting: Urban	Small town	X	Rural

This bridge was previously surveyed by the State Highway Administration in September 1995. The following is a revised version of the bridge inventory form prepared at that time.

Describe Setting:

Bridge No. 16015 carries MD 450 (Annapolis Road) over an abandoned railroad line in Prince George's County. MD 450 runs east-west and the abandoned railroad line extends north-south. The bridge is located in an area known as Buena Vista and is surrounded by woodland and single family dwellings to the southeast and northwest. Overhead utility lines traverse the railroad cut, parallel to both sides of the bridge. Other utility lines cross perpendicular under the bridge.

Describe Superstructure and Substructure:

Bridge No. 16015 is a 3-span, 2-lane, metal girder bridge constructed in 1931. The structure has span lengths of 35 feet, 37 feet and 35 feet with a total structure length of 107 feet. The bridge has a clear roadway width of 24 feet without sidewalks. The superstructure consists of nine (9) concrete encased, rolled girders which support a reinforced concrete deck and concrete parapets. The roadway is carried on the girders. The structure has pierced parapets and the roadway approaches have w-section guardrails which border the roadway and attach to the end blocks of the parapets. The substructure consists of two (2) concrete abutments and two (2) concrete pier columns. There are four (4) flared concrete wing walls. The bridge is posted for 29 tons, and has a sufficiency rating of 24.0.

According to the 1996 inspection report, this structure was in fair to poor condition with cracking, rusting and efflorescence. Seventy-five (75) percent of the deck is hollow sounding along with longitudinal and transverse cracking. The parapets have areas of spalling with exposed reinforcement bars. Both parapets have large areas of patches and cracking. Span 2 of the south parapet is slightly misaligned. The girders have light to heavy rust and scaling throughout. Both the abutments and the pier columns have vertical cracking with efflorescence. All of the wing walls have been patched and have random cracking.

Discuss Major Alterations:

According to the prior inventory form, the bridge was repaired in 1991/92. The repairs included patching the pier caps with gunite and replacing the wearing surface.

HISTORY:

WHEN was the bridge built:	1931	_
This date is: Actual	X	Estimated
Source of date: Plaque	Design plans	County bridge files/inspection form
Other (specify): State Highwa	y Administration bridg	ge files/inspection forms

WHY was the bridge built?

The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.

WHO was the designer?
Unknown
WHO was the builder?
Unknown
WHY was the bridge altered?
N/A
Was this bridge built as part of an organized bridge-building campaign?
Unknown
SURVEYOR/HISTORIAN ANALYSIS:
This bridge may have National Register significance for its association with: A - Events B- Person C- Engineering/architectural character

The bridge is not eligible for the National Register of Historic Places due to the severe deterioration of character defining elements.

Was the bridge constructed in response to significant events in Maryland or local history?

Metal girder bridges were most likely introduced and first popularized in Maryland by the state's major railroads of the nineteenth century including the Baltimore and Susquehanna, its successor the Northern Central, and the Baltimore and Ohio Railroad. Bridge engineering historians have documented the fact that James Milholland (or Mulholland) erected the earliest plate girder span in the United States on the Baltimore and Susquehanna Railroad in 1846 at Bolton Station, near present-day Mount Royal Station. The sides (web) and bottom flange of Milholland's 54-foot-long span were wholly of wrought iron and included a top flange reinforced with a 12x12-inch timber. Plates employed in the bridge were 6 feet deep and 38 inches wide, giving the entire bridge a total weight of some 14 tons. Milholland's pioneering plate girder cost \$2,200 (Tyrrell 1911:195). By December 31, 1861, the Northern Central Railroad, which succeeded the Baltimore and Susquehanna, maintained an operating inventory in Maryland of 50 or more bridges described simply as "girder" spans, in addition to a number of Howe trusses. Most of these were probably iron girder bridges; the longest were the 117-foot double-span bridge over Jones Falls and the 106-foot double-span girder bridge at Pierce's Mill (Gunnarson 1990:179-180).

As in the nation, girder bridge technology in Maryland was quickly adapted to cope with the increasingly heavy traffic demands of the twentieth century caused by automobile and truck traffic. The 1899 Maryland Geological Survey report on highways noted that "there are comparatively few I-beam bridges, one of the cheapest and best forms for spans less than 25 or 30 feet" (Johnson 1899:206). Interestingly, the report also urged construction of a composite metal, brick, and concrete bridge, noting that "no method of construction is more durable than the combination of masonry and I-beams, between which are transverse arches of brick, the whole covered with concrete, over which is laid the roadway" (Johnson 1899:206). Whether any such bridges (transitional structures between I-beams and reinforced concrete spans) were built is unknown.

Official state and county highway reports—issued between 1900 and the early 1920s through the Highway Division of the Maryland Geological Survey and its successor, the State Roads Commission—generally do not reference or describe girder construction. An analysis of the current statewide listing of county and municipal bridges (a listing maintained by the State Highway Administration) reveals that 48 county bridges, out of the total of 141 approximately dated to "1900" by county engineers, were listed as steel girder, steel stringer, or variants of such terms. (It should be noted that the "1900" date is often given when no exact date is pinpointed for a bridge that is clearly old). A grand total of 200 bridges (including "steel culverts"), out of 550 bridges dated on the county list between 1901 and 1930, were described as steel beam, steel girder, or steel stringer and girder varieties. The total suggests that among the various highway bridge types built in the early twentieth century metal girder bridges in Maryland between 1900 and 1930 were second in popularity only to reinforced concrete bridges. However, these numbers must be interpreted with caution, as they do not necessarily include all county and municipal bridges.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

A significant example of a metal girder bridge should possess character-defining elements of its type, and be readily recognized as an historic structure from the perspective of the traveler. The integrity of distinctive features visible from the roadway approach, including parapet walls or railings, is important in structures which are common examples of their type. In addition, the structure must be in excellent condition. This bridge, which suffers from severe deterioration of the character defining elements, is an undistinguished example of a metal girder bridge.

Does the bridge retain integrity of important elements described in Context Addendum?


The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including concrete encased rolled girders, concrete abutments and concrete piers, but severe deterioration is evident.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.





Inventory	#	PG:	70-	5	6

Name 16015-MO 450 OVER ABANDONED RR County/State PRINCE GEORGES COUNTY/MP Name of Photographer WALLY KING Date 195
Location of Negative 5HA
Description FAST APPROACIA LUOKING
Number 40 of 43



Inventory # <u>PG: 70-56</u>
Name 4015- MO 450 OVER ABANDONEO RR County/State PRINCE BEORGES COUNTY/MD Name of Photographer WALLY KING Date 195
Location of Negative SHA
Description WEST APPROACH LOOKING

Number 2 of 43

E STORY CONTRACTOR



Inventory	#	P	G	à E	70	(60°	5	4

Name 16015-MD-150 OVER ABANONED RR County/State PRINCE GEORGES COUNTY/MO Name of Photographer WALLY KING Date 1015
Location of Negative SHA
Description SOUTH ELEVATION
Number 3 of 43



Inventory # <u>PG:70-56</u>
LOUIS DIER ABANDONED RIC
Name 16015 PATO 450 WELL THE COUNTY MO Name of Photographer WALLY KING
Date 195
Location of Negative SHA
Description NURTH ELEVATION
Number 3 of 4

16-37

INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

	PG:70-56
Property/District Name: Bridge 16015	Survey Number: PG:70-2-
Project: MD 450:MD 193 to Seabrook Road	Agency: FHWA/SHA
Site visit by MHT Staff: X no yes Name	Date
Eligibility recommended Eligibility not recommended	mended <u>X</u>
Criteria:ABCD Considerations:AB	BCDEFGNone
Justification for decision: (Use continuation sheet if no	ecessary and attach map)
Based on the available information, Bridge No. 16015, MD anot appear to meet the National Register Criteria for indiconcerete encased metal girder bridge was constructed in and retains all of its character defining elements (CDEs). inspection by SHA bridge engineers, the bridge is in poor substructure deterioration and the superstructure is severe of the deck being hollow sounding, exposed reinforcing rusting, and section loss. According to the revised (9/30/96), the bridge does not retain integrity, because rehabilitation. To conclude, the bridge lacks sufficient in of the Criteria. Lastly, the bridge is not located in a listrict eligible for the National Register of Historic Pla as part of the MD 450 project.	ividual listing. The three span, 1931. It has pierced balustrades However, based on a July 18, 1996 condition. There is substantial ely deteriorated as well, with 75%, deteriorated concrete, severe inventory form prepared by SHA its CDEs are beyond the point of integrity to be eligible under any an area which would constitute a
The Interagency Bridge Committee determined the bridge to time, the bridge has continued to deteriorate and a recent the bridge as in overall poor condition. Based on this inventory form, it now appears that the bridge is not elig	inspection report (7/18/96) rated new information and the revised
Documentation on the property/district is presented in:Pro	oject file, Maryland Inventory
Form PG:70-3	
Prepared by:Jason Moser, SHA (1995), revised by James T.	Aquirre, SHA (1996)
Elizabeth Hannold Reviewer, Office of Preservation Services	October 15, 1996 Date
NR program concurrence: X yes no not applicable to the concurrence of the concurr	10 16 9 6 Date

70-56 Survey No. <u>PG: 70-2</u>

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I.	Geographic Region:		
X	Eastern Shore Western Shore Piedmont	(all Eastern Shore counties, and Cecil) (Anne Arundel, Calvert, Charles, Prince George's and St. Mary's) (Baltimore City, Baltimore, Carroll,	
	Western Maryland	Frederick, Harford, Howard, Montgomery) (Allegany, Garrett and Washington)	
II.	Chronological/Developmental Periods:		
	Paleo-Indian Early Archaic Middle Archaic Late Archaic Early Woodland Middle Woodland Late Woodland/Archaic Contact and Settlement Rural Agrarian Intensification Agricultural-Industrial Transi Industrial/Urban Dominance Modern Period Unknown Period (prehistor	A.D. 1870-1930 A.D. 1930-Present	
III.	Prehistoric Period Themes:	IV. Historic Period Themes:	
	Subsistence Settlement Political Demographic Religion Technology Environmental Adaption	Agriculture X Architecture, Landscape Architecture, and Community Planning Economic (Commercial and Industrial) Government/Law Military Religion Social/Educational/Cultural Transportation	
v. R	esource Type:		
	Category: Structure Historic Environment: Rural/Suburban		
	Historic Function(s) and Use(s	s): <u>Transportation-vehicular</u>	
	· · · · · · · · · · · · · · · · · · ·		
	Known Design Source: St	tate Roads Commission	

PG:70-56 Bridge #16015, MD 450 over Abandoned Railroad Annapolis Road (MD 450) Lanham quadrangle

